


BUILDING SAFETY CERTIFICATE

"It is certified that the visual inspections of the buildings occupied by Kendriya Vidyalaya, Dimapur, C/o HQ 3 Corps, 939 FPO have been inspected by the representative of GE 868 EWS and as on date the buildings are found safe for occupation". However, it is observed that the maint of the bldgs has not been carried out to upgrade the life of bldgs and also to address the unseen defects as the bldg is located in seismic Zone-V and non adherence to periodical maint may lead to some minor incidents.

Station : C/o 99 APO

Dated : 07 Dec 2020


(Ravi Tomar)
Maj
Garrison Engineer